VZCZCXYZ0000 RR RUEHWEB

DE RUEHMN #0213 1091641 ZNY SSSSS ZZH R 181641Z APR 08 FM AMEMBASSY MONTEVIDEO TO SECSTATE WASHDC 8118

S E C R E T MONTEVIDEO 000213

SIPDIS

DEPT. FOR WHA/BSC, DS/PSD/PCB, OBO/PD, DS/IP/WHA

E.O. 12958: DECL: 04/16/2018

TAGS: ASEC ABLD PTER UY
SUBJECT: AMEMBASSY MONTEVIDEO PHYSICAL SECURITY DEFICIENCIES AND FAST-TRACKING PROPOSED SECURITY UPGRADE

Classified By: RSO for reasons 1.4(g)

- $\underline{\mbox{1}}\mbox{1}.$ (U) This is an action cable. Please see paragraph 6.
- 12. (S) Embassy Montevideo is extremely concerned about the continued slippage in the start date for the embassy security upgrade projects firs
- 13. (S) First and foremost the chancery has insufficient setback and huge glass windows in most offices. Any explosion would undoubtedly result
- 14. (S) Secondly, because of the building configuration, all visa applicants/consular visitors pass through our central lobby, which faces/has
- 15. (S) In addition to these major deficiencies the RSO, after staging several Jeddah-scenario drills, has identified a significant vulnerabili
- 16. (S) Action Request: Embassy Montevideo requests that DS and OBO put priority on initiating and completing these vital security upgrades in Baxter